

# Oil Field Environmental Incident Summary

**Incident:** 20140701153500      **Date/Time of Notice:** 07/01/2014 15:35

**Responsible Party:** CONDOR PETROLEUM, INC.

**Well Operator:** CONDOR PETROLEUM, INC.

**Well Name:** L. MARIE SKARPHOL 3-1

**Field Name:** STONEVIEW

**Well File #:** 13423

**Date Incident:** 7/1/2014      **Time Incident:** 13:00

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 160

**Rng:** 95

**Sec:** 3

**Qtr:**

## Location Description:

**Submitted By:** Emily Drabbs

**Received By:**

**Contact Person:** Steve Tracey  
PO BOX 339  
417 2ND ST NE  
TIOGA, ND 58852

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 5 Mile

**Distance Nearest Water Well:** 5 Mile

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	20	Barrels				
Other					20	barrels

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 10/6/2015

**Clean Up Concluded:** 7/2/2014

**Risk Evaluation:**

No immediate risk

**Areal Extent:**

**Potential Environmental Impacts:**

Nearby wetlands--but should not be a problem as leak was stopped

**Action Taken or Planned:**

Leak was stopped, treater was drained, water will be sucked out and disposed of at nearby salt water tank

**Wastes Disposal Location:** Salt water tank, approx 50 feet from the spill.

**Agencies Involved:**

**Updates**

---

**Date:** 7/1/2014    **Status:** Reviewed - Assigned to Other Agency    **Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Spoke with company contact, and the spill remained on location within the dikes. NDIC retains oversight.